

Phone Booths installations  
to be relocated

Installation ID	Building #	Street	Corner of	# of Phones	Zip code	Obstructions/comments	DoITT's Comments	Remove		
								Yes	Remove	Maybe
15348	521	8 AVENUE		2	10018	1 on block 2 at intersection, In line of sight of turning vehicles, , 3 news boxes, pedestrians walk in the road --- Level F	4 installation at intersection, 2 installation in CB5, 2 installation in siting violation (272 W 36 St & 277 W 36 St) < 50'	✓		
15407	539	8 AVENUE		1	10018	4 at intersection, 2 on block, In line of sight of turning vehicles, , , pedestrians walk in the	5 installation at intersection, 2 installation mid block, 4 installation in CB5, 2 installation in siting violation (265 W 37 St., 266 W 37 St., & 550 8 Ave) < 50'	✓		
10827	575	8 AVENUE		2	10018	3 at intersection, 2 on block, In line of sight of turning vehicles, , , Double bike racks --- Post office Box pedestrians walk in the road --- Level F	5 installation at intersection, 3 installation in CB5, PPT at 270 W 38 St in siting violation < 8' sidewalk clearance, 2 Installations (270 West 38 Street & 560 8 Ave) < 50'	✓		
5621	601	8 AVENUE		1	10018	3 at intersection, 2 on block, , , 5 news boxes, garbage magnet pedestrians walk in the road --- Level F	4 installation at intersection, 1 installation in CB5, 2 installation in siting violation (601 8 Ave & 303 West 39 St.) < 50'	✓		
14344	791	8 AVENUE		1	10019	3 at Intersection, In line of sight of turning vehicles, , , Store installation on street, parking metered, single box, Less that 8ft of clearance pedestrians walk in the road --- Level F	5 installation at intersection, 2 installations in CB5, PPT at 791 8 Ave in siting violation < 8' sidewalk clearance, 2 installation in siting violation (300 West 48 Street & 787 8 Ave) < 50'	✓		
3936	831	8 AVENUE		1	10019	4 at Intersection, In line of sight of turning vehicles, , , Subway entrance pedestrians walk in the road --- Level F	4 installation at intersection, no siting violation, 2 installation in CB 5, PPT at 831 8 Ave in siting violation - in front of bldg. entrance.	✓		
3948	889	8 AVENUE		1	10019	3 at intersection, 3 on block, In line of sight of turning vehicles, , , pedestrians walk in the road --- Level F	4 installation at intersection, PPT at 888 8 Ave in siting violation < 15' from hydrant	✓		
10330	947	8 AVENUE		2	10019	2 on block and 2 at intersection, , , , parking meter pedestrians walk in the road --- Level F	3 installation at intersection, PPT at 235 W 56 St in siting violation < 15' from hydrant	✓		
14306	969	8 AVENUE		3	10019	3 at intersection, In line of sight of turning vehicles, , , Saturation and Safety pedestrians walk in the road --- Level F	4 installation at intersection, 1 installation mid block, PPT at 264 W 57 St in siting violation < 15' from a hydrant & bus stop shelter	✓		
5938	440	9 AVENUE		1	10001	3 at intersection, , , , Close to a large commercial building entrance/ exit , facing business entrance. Saturated - -- extremely narrow sidewalks see	3 installation at intersection, PPT at 440 9 Ave in siting violation - in front of building entrance, 2 installation 380 W 35 St & 440 9 Ave < 50'	✓	MBP support	Subject to lawsuit
10583	441	9 AVENUE		2	10018	3 at intersection, , , , too many at intersection. Space needed to plant a tree. Saturated --- extremely narrow	3 installation at intersection, PPT at 440 9 Ave in siting violation - in front of building entrance, 2 installation 380 W 35 St & 440 9	✓		
10718	502	9 AVENUE		2	10018	2 at intersection, 2 on block, , , 2 news boxes, two US boxes, magnet for garbage dumping. Proximity to	2 installation at intersection, no siting violation	✓	MBP support	Subject to lawsuit
10717	523	9 AVENUE		2	10018	3 at intersection, 2 on block, In line of sight of turning vehicles, , , facing restaurant entrance--- sandwich	3 installation at intersection, 526 9 Avenue in siting violation - in front of bldg. entrance	✓	MBP support	Subject to lawsuit
10639	526	9 AVENUE		2	10018	3 at intersection, 2 on block, , , 5 news boxes, 5 news boxes . Magnet for garbage, proximity to trap door,	3 installation at intersection, 526 9 Avenue in siting violation - in front of bldg. entrance	✓		
10720	542	9 AVENUE		2	10018	3 at intersection, 2 on block, , , 5 news boxes, 5 news boxes, massive garbage - pizza customers congregate	3 installation at intersection, no siting violation	✓	MBP support	Subject to lawsuit
6177	543	9 AVENUE		1	10018	3 at intersection, 2 on block, , , , facing business entrance. Magnet for crime . Numerous complaints from	3 installation at intersection, no siting violation	✓	MBP support	Subject to lawsuit
11006	568	9 AVENUE		2	10018	2 on block, , , , enormous amount of garbage	2 installation at intersection, 1 installation in siting violation (551 9 Avenue < than 15' from a fire hydrant)	✓		

Phone Booths installations  
to be relocated

Installation ID	Building #	Street	Corner of	# of Phones	Zip code	Obstructions/comments	DoITT's Comments	Remove		
								Yes	Remove	Maybe
14285	581	9 AVENUE		2	10018	4 at intersection, 2 on block, In line of sight of turning vehicles, , 3 news boxes, not operating Saturated --- extremely narrow sidewalks see cover notes	4 installation at intersection, no siting violation, PPT at 400 W. 42 St was temp removed.	✓	MBP support	
3836	600	9 AVENUE		1	10036	4 at intersection, 3 on block, In line of sight of turning vehicles, , 3 news boxes, Parking meter, bike rack, news boxes Saturated --- extremely narrow sidewalks see cover notes	4 installation at intersection, no siting violation	✓	MBP support	
11008	645	9 AVENUE	West 45th Street	2	10036	4 at intersection, 4 on block, , Sidewalk café, , not operating , blocks the view for drivers and pedestrians. takes up valuable sidewalk space. NW corner of 9th Avenue and 45th Street. Blind spot for drivers turning on to West 45th Street. Drivers cannot see peds crossing south	2 installation at intersection, 1 installation mid block, 651 9 Ave & 645 9 Ave in siting violation clear path 5' and 6'	✓		
1072	651	9 AVENUE		1	10036	4 at intersection, 3 on block, , Sidewalk café, , facing entrance to restaurant, bike parking , menu stand Saturated --- extremely narrow sidewalks see cover notes	2 installation at intersection, 1 installation mid block, 651 9 Ave & 645 9 Ave in siting violation clear path 5' and 6'	✓		
3921	665	9 AVENUE		1	10036	3 at intersection, , Galaxy Sidewalk café, , sandwich board Saturated --- extremely narrow sidewalks see cover notes	3 installation at intersection, no siting violation	✓	MBP support	
10698	683	9 AVENUE		2	10036	2 at intersection, In line of sight of turning vehicles, , , not operating , large double phone booth in front of	2 installation at intersection, 683 9 Avenue in siting violation clear path 5'	✓		
5915	761	9 AVENUE		1	10019	4 at intersection, In line of sight of turning vehicles, , , Directly across from commercial entrance (Chan Pen). Many bikes locked to phone	3 installation at intersection, PPT at 762 9 Ave is not present (site under construction), 2 installation in siting violation (761 9 Ave & 401 W 51 St) < 50'	✓	MBP support	Subject to lawsuit
10696	762	9 AVENUE		2	10019	4 at intersection, , , 3 news boxes, Directly across from commercial entrance (Petland). Near excessive news boxes. Used as a repository for bird food to attract pigeons Saturated --- extremely narrow sidewalks see cover notes	3 installation at intersection, PPT at 762 9 Ave is not present (site under construction), 2 installation in siting violation (761 9 Ave & 401 W 51 St) < 50'	✓		
10837	795	9 AVENUE		2	10019	4 at intersection, , , , Directly across from commercial entrance (Mee Noodle Shop). Saturated extremely narrow sidewalks see cover notes	4 installation at intersection, 1 installation mid block, PPT at 807 9 Ave in siting violation clear path 5'-2" & in front of bldg. entrance. 2 installation in siting violation (400 West 53 Street & 795 9 Ave) < 50' See # 77	✓	MBP support	Subject to lawsuit
10944	801	9 AVENUE		2	10019	3 on intersection and 3 on block, In line of sight of turning vehicles, , , Directly across from commercial entrance (Giorgio's Restaurant). Much garbage nearby Saturated --- extremely narrow sidewalks see cover notes	4 installation at intersection, 1 installation mid block, PPT at 807 9 Ave in siting violation clear path 5'-2" & in front of bldg. entrance. 2 installation in siting violation (400 West 53 Street & 795 9 Ave) < 50' See # 77	✓	MBP support	Subject to lawsuit
15420	807	9 AVENUE		1	10019	3 on block, , , , Directly across from commercial entrance (Bar Nine) with trapdoor. Sidewalk narrows Saturated --- extremely narrow sidewalks see cover notes	4 installation at intersection, 1 installation mid block, PPT at 807 9 Ave in siting violation clear path 5'-2" & in front of bldg. entrance. 2 installation in siting violation (400 West 53 Street & 795 9 Ave) < 50' See # 77	✓		
10685	815	9 AVENUE		2	10019	2 on intersection and 3 on block , In line of sight of turning vehicles, , , Directly across from commercial	2 installation at intersection, 2 installation in siting violation (401 W 54 St < 8' clear path & 815 9 Ave in front of bldg entrance)	✓		
3890	861	9 AVENUE		1	10019	3 on intersection, In line of sight of turning vehicles, Sidewalk café, 4	3 installation at intersection, 2 installation 400 W 56 St & 861 9 Ave < 50' See # 79	✓		
10761	735	10 AVENUE	50th		10019	3 at intersection , 2 on block , , , , Saturated --- there are 6 phones 3 on	4 installation at intersection, PPT at 501 W 50 St in siting violation < 15' from hydrant	✓		
5922	125	25th Street	6 AVENUE		10001	1 on block , , , , Safety --- Large Homeless shelter few feet away. It is	Phone booth may be replaced with Link (no shelter)	✓	MBP support	Subject to lawsuit

Phone Booths installations  
to be relocated

Installation ID	Building #	Street	Corner of	# of Phones	Zip code	Obstructions/comments	DoITT's Comments	Remove		
								Yes	Remove	Maybe
10220	402	WEST 44 STREET	9 AVENUE	2	10036	1 on intersection , In line of sight of turning vehicles, Sidewalk café , The phone booth not only blocks the	3 installation at intersection, no siting violation	✓	MBP support	
15243	401	WEST 48 STREET	9 AVENUE	1	10036	3 at intersection, In line of sight of turning vehicles, , The phone booth blocks the view of drivers turning left onto 48th Street. 9AV here is downhill, so cars take the turn fast,	2 installation at intersection, no siting violation, PPT at 401 W 48 St was temp removed due to construction 7-2013. Construction completed per inspection 9-2015 - Phone has not been reinstalled.	✓		
10352	401	WEST 51 STREET	9 AVENUE	2	10019	4 at intersection, , , 3 news boxes, Excessive news boxes nearby. Around	3 installation at intersection, 2 installation (761 9 Ave & 401 W 52 St) < 50'	✓		
14345	310	WEST 52 STREET	8 AVENUE	1	10019	3 at intersection, 3 on block , In line of sight of turning vehicles, , 1 news	4 installation at intersection, 1 installation mid block, no siting violation	✓		
4094	401	WEST 52 STREET	9 AVENUE	1	10019	2 at intersection, , Sidewalk café , Directly across from commercial entrance. Sidewalk narrow	2 installation at intersection, 401 W 52 St in siting violation sidewalk clearance < 8'	✓		
3946	400	WEST 53 STREET	9 AVENUE	1	10019	4 at intersection, , , , Sidewalk narrows.	4 installation at intersection, 1 installation mid block, PPT at 807 9 Ave in siting violation clear path 5'-2" & in front of bldg. entrance. 2 installation in siting violation (400 West 53 Street & 795 9 Ave) < 50' <b>See # 33 - 39</b>	✓		
3929	401	WEST 54 STREET	9 AVENUE	1	10019	2 on intersection, , Sidewalk café , Directly across from commercial entrance (Oscar L. Bodega) with fruit	2 installation at intersection, 401 W 54 St clear path is 5'-9"	✓		